

PRODUCT CHANGE NOTIFICATION

PRODUCT CHANGE NOTIFICATION NUMBER: PC000040

PCN DATE: Nov. 6, 2025

This notice is to inform you about the following changes to the listed Stewart Connector products. For any further questions about these changes, please contact your Stewart Connector sales contact, or customer service representative.

PARTS AFFECTED:

RJP50005AA-A RJP50005AB-A RJP50010AA-A RJP50010AB-A RJP50015AA-A RJP50015AB-A
RJP50020AA-A RJP50020AB-A RJP50025AA-A RJP50025AB-A RJP50030AA-A RJP50030AB-A
RJP50040AA-A RJP50040AB-A RJP50050AA-A RJP50050AB-A RJP5005AB-A RJP50075AA-A
RJP50075AB-A RJP50100AA-A RJP50100AB-A RJP50125AA-A RJP50125AB-A RJP50150AA-A
RJP50150AB-A RJP50350AB-A RJP5-16-0001


REPLACEMENT PART: No Replacement

GENERAL PRODUCT DESCRIPTION:

All RJ.5 (half-size RJ45) products with male plugs

REASON FOR CHANGE:

We are no longer able to source the strain relief boots for these RJ.5 plugs.



DESCRIPTION OF CHANGES:

Due to this strain relief material shortage, we will not be able to continue to produce these RJP5 cable assembly products.

ESTIMATED IMPLEMENTATION DATE:

Effective immediately

SIGNATURE:

A handwritten signature in black ink, appearing to read "Tim Kurten".

Tim Kurten
Product Manager